

Application No.:10/782,574

Docket No.: JCLA12196

In The Specification:

Please amend the following paragraphs as follows.

[0004] On the other hand, the color mixing light 102 enters a color splitter again to be split into a red beam 108 and a green beam 110. ~~When~~ When the red beam 108 and the green beam 110 are split, the light paths are similar to the blue beam 104, and respectively enter the PBS 158r and 158g as well as the LCOS panels 160r and 160g, so as to form the image patterns with respect to the primary colors.

[0030] There are several problems with ~~For the conventional design shown in FIG. 4,~~ ~~after analyses by the invention, there are several problems found.~~ For example, if WGP 320 is bent due to non-uniform thermal expansion or other reasons, ~~it causes the reflection~~ reflected beam ~~being will~~ will not be parallel. This ~~would then~~ causes serious lateral color aberration.